

Inspection Photos

API: 071-08567

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/8/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08567 | Date: 1/8/2021

Inspection Photos



Photo 1. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08567 | Date: 1/8/2021

Inspection Photos



Photo 2. Facing south at the location. Vegetation is well established in Interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08567 | Date: 1/8/2021

Inspection Photos



Photo 3. Facing toward the well. Unused pipe next to the well will need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08567 | Date: 1/8/2021

Inspection Photos



Photo 4. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08567 | Date: 1/8/2021

Inspection Photos



Photo 5. Facing toward the south side of the location. Vegetation is well established in Interim reclamation area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08567 | Date: 1/8/2021