

Location Name: ADAMIC 1-20, API #: 043-06020, Insp. #:695103790



Colorado Oil & Gas Conservation Commission

303-278-9900 105-12874-1502 Op 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 1: LOCATION



SAN MARCO PETROLEUM, INC.
Denver, CO



Adamic 1-20 Well
API #043-06020
NESE 20-T19S-R69W
Fremont County, Colorado

EMERGENCY CONTACTS

911
719-568-1902
303-905-5919
303-321-0100

Colorado Oil & Gas Conservation Commission
38.37891, -105.12874, 1589.0m, 299°



Colorado Oil & Gas Conservation Commission

38.37903, -105.12838, 1581.0m, 308°

2021/01/11 12:39:21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 3: BRADENHEAD IS NOT PLUMBED TO SURFACE. PLUMB BRADENHEAD TO SURFACE, COMPLY WITH RULE 341. CA DATE 3-11-21.



Colorado Oil & Gas Conservation Commission

38.37903, -105.12838, 1581.0m, 308°

2021/01/11 12:39:21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 4: IT APPEARS WELLHEAD IS LEAKING THERE IS AN AREA OF IMPACTED SOIL APP. 6' X 3' AROUND WELLHEAD. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 3-11-21.



Colorado Oil & Gas Conservation Commission

38.37898, -105.12844, 1579.0m, 260°

2021/01/11 12:48:44



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 5: THERE IS AN AREA OF IMPACTED SOIL NEAR NORTHERN MOST CRUDE OIL TANK APPEARS VALVE HAS BEEN REPLACED BUT NOT ALL THE IMPACTED SOIL HAS BEEN REMOVE. **Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 3-11-21.**



Colorado Oil & Gas Conservation Commission

38.38867, -105.11694, 339°

2021/01/11 12:53:40



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 6: AREA OF IMPACTED SOIL NEAR CRUDE OIL LOADOUT. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 3-11-21.



Colorado Oil & Gas Conservation Commission

38.37906, -105.12861, 1574.0m, 294°

2021/01/11 12:47:17



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 7: TRASH IN SEVERAL PLACES AROUND LOCATION. POLICE ON AND AROUND ENTIRE LOCATION OF ANY TRASH, COMPLY WITH RULE 603.f. CA DATE 3-11-21.



Colorado Oil & Gas Conservation Commission

38.37904, -105.1287, 1570.0m, 114°

2021/01/11 13:19:41



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 8: CRUDE OIL SIGN IS DAMAGED ON NORTHERN MOST CRUDE OIL TANK. **POST SIGN, COMPLY WITH RULE 210. d.**
CA DATE 3-11-21.



Colorado Oil & Gas Conservation Commission

38.37904, -105.1287, 1570.0m, 77°

2021/01/11 13:19:59



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Phone 8: CRUDE OIL SIGN IS MISSING ON SOUTHERN MOST CRUDE OIL TANK. **POST SIGN, COMPLY WITH RULE 210. d. CA DATE 3-11-21.**