

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611




Photo 1 – Tank Battery Sign

Photo 2 – Wellhead

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 3 – Pumping Unit



Photo 4 – Separator

Inspection Photos
Location Name: Pronghorn P-T-22HNB
Location ID: 432611



Photo 5 – Tank Battery



Photo 6 – Gas Meter, EDC

Inspection Photos
Location Name: Pronghorn B-24 PAD
Location ID: 437037



Photo 7 – Risers have been marked