

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 1 – Wellhead



Photo 2 – Separators

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 3 – ECDs




Photo 4 – Unmarked Risers on NE/East side of Location

Inspection Photos
Location Name: Pronghorn 31-34-6HZ
Location ID: 427009



Photo 5 – Unmarked Risers on NE/East side of Location




Photo 6 – Unmarked Risers on NE/East side of Location



Inspection Photos
Location Name: Pronghorn 31-34-6HZ
Location ID: 427009



Photo 7 – Unmarked Risers on NE/East side of Location




Photo 8 – Unmarked Risers on NE/East side of Location



Inspection Photos
Location Name: Pronghorn 31-34-6HZ
Location ID: 427009




Photo 9 – Unmarked Risers on NE/East side of Location