

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2021

Submitted Date:

01/12/2021

Document Number:

693504164

**FIELD INSPECTION FORM**

Loc ID 456747	Inspector Name: Silver, Randy	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> <div style="border: 1px solid black; padding: 2px;"> 4    Number of Comments  0    Number of Corrective Actions  <input type="checkbox"/> Corrective Action Response Requested </div>																																																																																																																								
<b>Operator Information:</b> OGCC Operator Number: 10459 Name of Operator: EXTRACTION OIL & GAS INC Address: 370 17TH STREET SUITE 5200 City: DENVER    State: CO    Zip: 80202				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																																																								
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>,</td> <td></td> <td>COGCCInspections@extracti onog.com</td> <td>All Inspectors</td> </tr> </table>					Contact Name	Phone	Email	Comment	,		COGCCInspections@extracti onog.com	All Inspectors																																																																																																																
Contact Name	Phone	Email	Comment																																																																																																																									
,		COGCCInspections@extracti onog.com	All Inspectors																																																																																																																									
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>456736</td><td>WELL</td><td>DG</td><td>09/25/2019</td><td></td><td>014-20759</td><td>INTERCHANGE A S22-30-13C</td><td>DG</td></tr> <tr><td>456737</td><td>WELL</td><td>DG</td><td>09/23/2019</td><td></td><td>014-20760</td><td>INTERCHANGE A S22-30-10C</td><td>DG</td></tr> <tr><td>456738</td><td>WELL</td><td>DG</td><td>09/20/2019</td><td></td><td>014-20761</td><td>INTERCHANGE A S22-30-6N</td><td>DG</td></tr> <tr><td>456739</td><td>WELL</td><td>DG</td><td>09/23/2019</td><td></td><td>014-20762</td><td>INTERCHANGE A S22-30-11N</td><td>DG</td></tr> <tr><td>456740</td><td>WELL</td><td>DG</td><td>09/20/2019</td><td></td><td>014-20763</td><td>INTERCHANGE A S22-30-5N</td><td>DG</td></tr> <tr><td>456741</td><td>WELL</td><td>DG</td><td>09/18/2019</td><td></td><td>014-20764</td><td>INTERCHANGE A S22-30-2N</td><td>DG</td></tr> <tr><td>456742</td><td>WELL</td><td>DG</td><td>09/24/2019</td><td></td><td>014-20765</td><td>INTERCHANGE A S22-30-12N</td><td>DG</td></tr> <tr><td>456743</td><td>WELL</td><td>DG</td><td>09/21/2019</td><td></td><td>014-20766</td><td>INTERCHANGE A S22-30-8N</td><td>DG</td></tr> <tr><td>456744</td><td>WELL</td><td>DG</td><td>09/18/2019</td><td></td><td>014-20767</td><td>INTERCHANGE A S22-30-3N</td><td>DG</td></tr> <tr><td>456745</td><td>WELL</td><td>DG</td><td>09/21/2019</td><td></td><td>014-20768</td><td>INTERCHANGE A S22-30-7C</td><td>DG</td></tr> <tr><td>456746</td><td>WELL</td><td>DG</td><td>09/19/2019</td><td></td><td>014-20769</td><td>INTERCHANGE A S22-30-4C</td><td>DG</td></tr> <tr><td>456748</td><td>WELL</td><td>DG</td><td>09/18/2019</td><td></td><td>014-20770</td><td>INTERCHANGE A S16-20-19C</td><td>DG</td></tr> <tr><td>456749</td><td>WELL</td><td>DG</td><td>09/22/2019</td><td></td><td>014-20771</td><td>INTERCHANGE A S22-30-9N</td><td>DG</td></tr> <tr><td>468826</td><td>WELL</td><td>XX</td><td>10/23/2019</td><td></td><td>014-20849</td><td>INTERCHANGE A S16-20-20N</td><td>XX</td></tr> </tbody> </table>					Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	456736	WELL	DG	09/25/2019		014-20759	INTERCHANGE A S22-30-13C	DG	456737	WELL	DG	09/23/2019		014-20760	INTERCHANGE A S22-30-10C	DG	456738	WELL	DG	09/20/2019		014-20761	INTERCHANGE A S22-30-6N	DG	456739	WELL	DG	09/23/2019		014-20762	INTERCHANGE A S22-30-11N	DG	456740	WELL	DG	09/20/2019		014-20763	INTERCHANGE A S22-30-5N	DG	456741	WELL	DG	09/18/2019		014-20764	INTERCHANGE A S22-30-2N	DG	456742	WELL	DG	09/24/2019		014-20765	INTERCHANGE A S22-30-12N	DG	456743	WELL	DG	09/21/2019		014-20766	INTERCHANGE A S22-30-8N	DG	456744	WELL	DG	09/18/2019		014-20767	INTERCHANGE A S22-30-3N	DG	456745	WELL	DG	09/21/2019		014-20768	INTERCHANGE A S22-30-7C	DG	456746	WELL	DG	09/19/2019		014-20769	INTERCHANGE A S22-30-4C	DG	456748	WELL	DG	09/18/2019		014-20770	INTERCHANGE A S16-20-19C	DG	456749	WELL	DG	09/22/2019		014-20771	INTERCHANGE A S22-30-9N	DG	468826	WELL	XX	10/23/2019		014-20849	INTERCHANGE A S16-20-20N	XX
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																					
456736	WELL	DG	09/25/2019		014-20759	INTERCHANGE A S22-30-13C	DG																																																																																																																					
456737	WELL	DG	09/23/2019		014-20760	INTERCHANGE A S22-30-10C	DG																																																																																																																					
456738	WELL	DG	09/20/2019		014-20761	INTERCHANGE A S22-30-6N	DG																																																																																																																					
456739	WELL	DG	09/23/2019		014-20762	INTERCHANGE A S22-30-11N	DG																																																																																																																					
456740	WELL	DG	09/20/2019		014-20763	INTERCHANGE A S22-30-5N	DG																																																																																																																					
456741	WELL	DG	09/18/2019		014-20764	INTERCHANGE A S22-30-2N	DG																																																																																																																					
456742	WELL	DG	09/24/2019		014-20765	INTERCHANGE A S22-30-12N	DG																																																																																																																					
456743	WELL	DG	09/21/2019		014-20766	INTERCHANGE A S22-30-8N	DG																																																																																																																					
456744	WELL	DG	09/18/2019		014-20767	INTERCHANGE A S22-30-3N	DG																																																																																																																					
456745	WELL	DG	09/21/2019		014-20768	INTERCHANGE A S22-30-7C	DG																																																																																																																					
456746	WELL	DG	09/19/2019		014-20769	INTERCHANGE A S22-30-4C	DG																																																																																																																					
456748	WELL	DG	09/18/2019		014-20770	INTERCHANGE A S16-20-19C	DG																																																																																																																					
456749	WELL	DG	09/22/2019		014-20771	INTERCHANGE A S22-30-9N	DG																																																																																																																					
468826	WELL	XX	10/23/2019		014-20849	INTERCHANGE A S16-20-20N	XX																																																																																																																					

468827	WELL	XX	10/23/2019		014-20850	INTERCHANGE A S22-30-1C	XX
468829	WELL	XX	10/23/2019		014-20852	INTERCHANGE A S22-30-21N	XX

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Steel rod panels		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>456736</u>	Type: <u>WELL</u>	API Number: <u>014-20759</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456737</u>	Type: <u>WELL</u>	API Number: <u>014-20760</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456738</u>	Type: <u>WELL</u>	API Number: <u>014-20761</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456739</u>	Type: <u>WELL</u>	API Number: <u>014-20762</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456740</u>	Type: <u>WELL</u>	API Number: <u>014-20763</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456741</u>	Type: <u>WELL</u>	API Number: <u>014-20764</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456742</u>	Type: <u>WELL</u>	API Number: <u>014-20765</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456743</u>	Type: <u>WELL</u>	API Number: <u>014-20766</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456744</u>	Type: <u>WELL</u>	API Number: <u>014-20767</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456745</u>	Type: <u>WELL</u>	API Number: <u>014-20768</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456746</u>	Type: <u>WELL</u>	API Number: <u>014-20769</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456748</u>	Type: <u>WELL</u>	API Number: <u>014-20770</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>456749</u>	Type: <u>WELL</u>	API Number: <u>014-20771</u>	Status: <u>DG</u>	Insp. Status: <u>DG</u>
Facility ID: <u>468826</u>	Type: <u>WELL</u>	API Number: <u>014-20849</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>468827</u>	Type: <u>WELL</u>	API Number: <u>014-20850</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>468829</u>	Type: <u>WELL</u>	API Number: <u>014-20852</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
COGCC Comments				
Comment	User	Date		
Routine inspection. At time of inspection the 13 DG wells appear to have surface pipe drilled. Cellars are covered with hog fence and surface pipe is caped with steel plate. At time of inspection XX show now evidence of being drilled.	silverr	01/12/2021		
Attached Documents				
You can go to COGCC Images ( <a href="https://cogcc.state.co.us/weblink/">https://cogcc.state.co.us/weblink/</a> ) and search by document number:				

Document Num	Description	URL
693504165	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327750">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5327750</a>