

Inspection Photos
Location Name: North Washington # 8-23
Location ID: 336041



Photo 1 Well heads



Photo 2 TNK BTRY

Inspection Photos
Location Name: North Washington # 8-23
Location ID: 336041



Photo 3 sep/ meter run and ECDs



Photo 4 approx 100psi on sales line.

Inspection Photos
Location Name: North Washington # 8-23
Location ID: 336041



Photo 5 Calibration card out of date 2014 and gas meter does not appear to be in operation.