

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402480195

Date Received:
09/02/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>		<u>sabre.beebe@bpx.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 695103003
Inspection Date: 07/22/2020 FIR Submit Date: 07/29/2020 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306873

Location Name: LEPLATT GAS UNIT B-N34N7W Number: 11SWNE County: LA PLATA
Qtrqtr: SWNE Sec: 11 Twp: 34N Range: 7W Meridian: N
Latitude: 37.232514 Longitude: -107.602589

FACILITY - API Number: 05-067-00 Facility ID: 271492

Facility Name: LE PLATT B Number: 1
Qtrqtr: SWNE Sec: 11 Twp: 34N Range: 7W Meridian: N
Latitude: 37.232514 Longitude: -107.602589

CORRECTIVE ACTIONS:

1 CA# 140795

Corrective Action: REMOVE NOXIOUS WEEDS COMPLY WITH RULE 1003.f. Date: 07/29/2020

Response: CA COMPLETED Date of Completion: 07/29/2020

Initial inspection received on 7/29/20 with due date of 7/29/20. a crew for weed removal was mobilized to location at the earliest availability to remove weeds. See attached.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 140796

Corrective Action: Comply with Rule 1102.f.(2) for best self inspection, maintenance and housekeeping to prevent breakdown or failure of BMP's. CA DATE IS ORIGINAL FROM PREVIOUS INSPECTION DOC#687904818

Date: 07/29/2020

Response: CA COMPLETED

Date of Completion: 08/19/2020

Operator Comment: Muffler hose repaired and muffler box installed to capture exhaust. See attached. Stained soils removed and disposed of in BP soil box for remediation at IEL in New Mexico

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed see attached. due date was same day inspection email was received and could not be met as excavation requires a clear and valid one call which requires time to submit and have cleared through 811 process for safe execution of work.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Sabre Beebe

Date: 9/2/2020 6:45:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402480195	FIR RESOLUTION SUBMITTED
402480196	Work completion document

Total Attach: 2 Files