

Inspection Photos

API: 099-06139

Operator: CHURCHILL ENERGY INC

Inspection Date: 1/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing east toward the location. The tank has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021

Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06139 | Date: 1/12/2021