

# Inspection Photos

API: 099-06135

Operator: BIG FOUR PETROLEUM CO

Inspection Date: 1/12/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021

## Inspection Photos



**Photo 1.** Facing east toward the location. There is barb wire debris that remains. There is pipeline equipment that remains at the location shown at red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021

## Inspection Photos



**Photo 2.** Pipeline riser equipment remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021

## Inspection Photos



**Photo 4.** Facing north. Pipeline riser equipment remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021

## Inspection Photos



**Photo 4.** Pipe risers and meter shed remain. All equipment must be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021

## Inspection Photos



**Photo 5.** There is wood debris that remains at the east side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021

## Inspection Photos



**Photo 6.** Facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 099-06135 | Date: 1/12/2021