

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133

Jan 14, 2021 at 12:21:22 PM
39.913920,-104.505900
Bennett CO 80102
United States
COGCC



Pic 1 weeds unmanaged


Jan 14, 2021 at 12:23:21 PM
39.913256,-104.507861
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 2 weeds unmanaged

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133

Jan 14, 2021 at 12:23:42 PM
39.912970,-104.507837
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 3 weeds unmanaged

Jan 14, 2021 at 12:23:56 PM
39.912871,-104.507850
Peterson Rd
Bennett CO 80102
United States
COGCC



Pic 4 trash on location

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 5 no labels on open top tank



Pic 6 no netting on open top tank / hydrocarbons present

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 7 no netting on open top tank / hydrocarbons present



Pic 8 what appears to be dead bird of prey in open top tank

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 9 what appears to be dead bird of prey in open top tank



Pic 10 What appears to be dead bird of prey in open tank