

Final Reclamation Inspection

January 14, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 422552

Inspection Document #: 697502441

Weld County, CO

SENE Section 23 T8N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 1. Photo taken from the southern access road, facing South. Photo illustrates Operator field crew commencing final reclamation activities.





Photo 2. COGCC GISOnline aerial imagery from 2019 illustrates the access road which has not been reclaimed per Rule 1004. On 1/14/2021, Operator was commencing final reclamation activities to reclaim the above access road.

Inspection Photos

Location Name: KUMMER PC LE #23-17

Location ID: 422552



Photo 3. Reference photo taken on 1/5/2021 east of the DA location, facing East. Photo illustrates the reference vegetation is mostly comprised of blue grama with some western wheatgrass, sand dropseed, and purple three-awn.

