



39.91303, -108.25596, 6636.0ft, 326°
01/14/2021 01:57:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Processing buidlings.

API: 05-103-11043 to 11054
Piceance Creek Unit 297-2A Inspection: 700405004



39.9121, -108.25537, 6640.2ft, 76°
01/14/2021 01:54:22 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

API: 05-103-11043 to 11054
Piceance Creek Unit 297-2A Inspection: 700405004



39.91229, -108.25539, 6638.4ft, 72°
01/14/2021 01:55:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Manifold.

API: 05-103-11043 to 11054
Piceance Creek Unit 297-2A Inspection: 700405004