

Inspection Photos  
Operator: Logos Operating  
API: 067-05430  
Date: 1/6/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Location is largely snow covered.



Photo 3. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, and narrow leaf penstemon.