

Inspection Photos  
Location Name: Pappenheim 6-62-23 PAD  
Location ID: 432757



Colorado Oil and Gas Conservation Commission  
40.47976, -104.29134, 4602.5ft, 228°  
01/12/2021 12:48:17



Colorado Oil and Gas Conservation Commission  
40.47983, -104.29229, 4670.4ft, 280°  
01/12/2021 12:59:13

Photo 1 – Pumping Units

Photo 2 – Tank Battery Signs

**Inspection Photos**  
**Location Name: Pappenheim 6-62-23 PAD**  
**Location ID: 432757**



Colorado Oil and Gas Conservation Commission  
40.47986, -104.29248, 4672.5ft, 19°  
01/12/2021 13:00:02



Colorado Oil and Gas Conservation Commission  
40.47985, -104.29232, 4680.8ft, 238°  
01/12/2021 12:59:45

**Photo 3 – Tank Battery**

**Photo 4 – Separators and VRTs**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-23 PAD**  
**Location ID: 432757**



**Photo 5 – Stained Soil at East VRU**

**Photo 6 – Stained Soil at East VRU**



**Inspection Photos**  
**Location Name: Pappenheim 6-62-23 PAD**  
**Location ID: 432757**



**Photo 7 – Unmarked Risers (Marking has faded)**

**Photo 8 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-23 PAD**  
**Location ID: 432757**



**Photo 9 – Unmarked Riser**

**Photo 10 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-23 PAD**  
**Location ID: 432757**



**Photo 11 – Unmarked Riser**

**Photo 12 – Unmarked Risers**

**Inspection Photos**  
**Location Name: Pappenheim 6-62-23 PAD**  
**Location ID: 432757**



**Photo 13 – Unmarked Riser**

**Photo 14 – ECDs**