

Inspection Photos
Location Name: Degenhart AE 16-63HN PAD
Location ID: 423230



Photo 1 – Pumping Units



Photo 2 – Separators, ECDS, and Gas Meters



Inspection Photos
Location Name: Degenhart AE 16-63HN PAD
Location ID: 423230



Photo 3 – Tank Battery



Photo 4 – South Engine



Inspection Photos
Location Name: Degenhart AE 16-63HN PAD
Location ID: 423230



Photo 5 – Stained Soil at North Engine