

Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Photo 1 – Pumping Unit

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Photo 3 – Tank Battery

Photo 4 – Heater Treater and ECD

Inspection Photos
Location Name: Frank Trust 11-11H
Location ID: 420027



Colorado Oil and Gas Conservation Commission
40.50885, -104.18535, 4666.3ft, 172°
01/13/2021 12:12:41



Colorado Oil and Gas Conservation Commission
40.50917, -104.18535, 4662.3ft, 268°
01/13/2021 12:12:09

Photo 5 – Risers have been marked

Photo 6 – Tubing Strings have been removed