



39.89675, -108.2449, 6997.0ft, 297°
01/14/2021 02:31:20 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Well location.

API: 05-103-10588 to 10593
Piceance Creek Unit T66X-11G Inspection: 700405010



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Wells.

API: 05-103-10588 to 10593
Piceance Creek Unit T66X-11G Inspection: 700405010



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Chemical, tank, building.

API: 05-103-10588 to 10593
Piceance Creek Unit T66X-11G Inspection: 700405010



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator & tank.

API: 05-103-10588 to 10593
Piceance Creek Unit T66X-11G Inspection: 700405010



39.89727, -108.24569, 6990.1ft, 19°
01/14/2021 02:37:24 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank.

API: 05-103-10588 to 10593
Piceance Creek Unit T66X-11G Inspection: 700405010