


Inspection Photos
Location Name: Gosney #1A
API: 05-067-09255



#2A location sign is missing operator contact information.



Production equipment on location. Northern separator appears to not have wildlife protections in place.

Inspection Photos
Location Name: Gosney #1A
API: 05-067-09255



Tank battery signs have previous operator listed.



Secondary containment for chemical containers.

Inspection Photos
Location Name: Gosney #1A
API: 05-067-09255



#4A well head with staining and white residue.



#2A well head with staining and white residue.

Inspection Photos
Location Name: Gosney #1A
API: 05-067-09255



Stained concrete pad and surrounding gravel near pump jack for the #2A.



Concrete pads at both pump jacks are stained and wet.