

Inspection Photos
Location Name: Ptasynski 3
Location ID: 312952



Photo 1. Access road not maintained for winter.

