

**Inspection Photos**  
**Location Name: McCallum Unit 67**  
**Location ID: 324619**



**Photo 1. Overview of location taken facing northeast.**



Inspection Photos  
Location Name: McCallum Unit 67  
Location ID: 324616



Photo 2. Emergency contact information torn off sign.



Photo 3. No bradenhead access apparent.

