

Final Reclamation Inspection

January 14, 2021

Operator: CARRIZO NIOBRARA LLC - #10439

Location ID: 405863

Inspection Document #: 697502461

Weld County, CO

NESW Section 36 T9N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 1. Photo taken from the well location entrance, facing East. Photo illustrates Operator has not removed all gravel but vegetation has started to establish but is not reflective of reference areas.

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 2. Close up photo taken from the well location entrance. Photo illustrates the remaining gravel and the establishment of blue grama, sand dropseed and purple three-awn.

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 3. Photo taken from the northeastern well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 4. Photo taken from the central well location, facing West. Photo illustrates a bare patch with no vegetation establishment. It does not appear the Operator has performed any further final reclamation activities in response to the previous corrective action inspection.

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 5. Photo taken from the southern well location, facing South. See comments under Photo 4.

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 6. Photo taken from the southern well location, facing Southeast. See comments under Photo 4.

Inspection Photos
Location Name: Sohio State #1
Location ID: 405863



Photo 7. Reference photo taken north of the well location, facing West.