

Inspection Photos
Location Name: Pappenheim 6-62-26-0108BH
Location ID: 432385




Photo 1 – Wellhead, unused Wellhead parts

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Pappenheim 6-62-26-0108BH
Location ID: 432385




Photo 3 – Tank Battery, Crude Oil Tank missing Labels

Photo 4 – Tank Battery, Crude Oil Tank missing Labels

Inspection Photos
Location Name: Pappenheim 6-62-26-0108BH
Location ID: 432385



Photo 5 – Risers have been marked

Photo 6 – Unmarked 1” Risers at Wellhead

Inspection Photos
Location Name: Pappenheim 6-62-26-0108BH
Location ID: 432385




Photo 7 – Separator, ECD

Photo 8 – Unmarked Risers