

Inspection Photos
Operator: Simcoe
API: 067-08679
Date: 1/14/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing, largely with grasses such as sand dropseed, western wheatgrass, and smooth brome.



Photo 3. View of the reference area comprised of mixed ponderosa pine and pinyon/juniper woodland with gambel oak and mountain mahogany shrubs, and grasses/forbs such as squirreltail and Colorado rubberplant.