

Inspection Photos  
Operator: Simcoe  
API: 067-07425  
Date: 1/14/2021



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Vegetation is largely snow covered and should be assessed during the active growing season.





Photo 3. View of kochia debris along the eastern edge of the project area. Inset shows more weed debris in the northeastern project area.





Photo 4. View of the reference area comprised of mixed ponderosa pine and pinyon/juniper woodland with gambel oak and mountain mahogany shrubs, and grasses/forbs such as squirreltail and Colorado rubberplant.