

Inspection Photos
Location Name: PHINNEY-66N64W /10NESE
Location #: 305859



Colorado Oil & Gas Conservation Commission
Weld
+40.499695, -104.528661
153° SE
13-Jan-2021 10:40

Photo #1

Phinney 43-10 (05-123-23590) Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | Final Plugging



Colorado Oil & Gas Conservation Commission
96° E
13-Jan-2021 14:21

Photo #2

Phinney 43-10 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | Final Plugging
Cement to surface
NOT Cut & Capped

Inspection Photos
Location Name: PHINNEY-66N64W /10NESE
Location #: 305859



Colorado Oil & Gas Conservation Commission
Weld
+40.499540, -104.528097
289° W
12-Jan-2021 14:59

Photo #3
Phinney 43-10 Wellsite
Plugged & Abandoned | PA
Jobsite safety signage
prior insp.