

Inspection Photos

API: 099-06125

Operator: BERRY ENERGY INC

Inspection Date: 1/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021

Inspection Photos



Photo 1. Facing east along the former access road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021

Inspection Photos



Photo 2. Facing east toward the location. The location fence remains around the location and is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021

Inspection Photos



Photo 3. Facing northeast at the location. The location has not been reclaimed. Equipment has not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021

Inspection Photos




Photo 4. Pipe risers and meter shed remain. All equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021

Inspection Photos



Photo 5. Pipe risers, meter shed, and separator tank remains. All equipment must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021

Inspection Photos



Photo 6. Facing north toward the location. The location has not been reclaimed. There is undesirable weeds and areas bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 099-06125 | Date: 1/12/2021