



39.88795, -108.43277, 6828.2ft, 318°
01/15/2021 02:35:45 PM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

RGU 33-7-198

API: 05-103-10610

Inspection: 700405028



39.88863, -108.43256, 6839.6ft, 31°
01/15/2021 02:34:03 PM



39.88823, -108.43315, 6827.7ft, 17°
01/15/2021 02:38:46 PM



39.88818, -108.4328, 6845.0ft, 209°
01/15/2021 02:37:39 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Base of condensate tank.

RGU 33-7-198

API: 05-103-10610

Inspection: 700405028



39.88819, -108.43291, 6847.3ft, 109°
01/15/2021 02:36:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tanks.

RGU 33-7-198

API: 05-103-10610

Inspection: 700405028