



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	LOCATION		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

Type	#		corrective date
Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:	Shares containment with crude oil tanks.				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	110 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV CONCRETE		
Comment: Shares containment with crude oil tanks.					
Corrective Action:					Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)	48 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.312500,-104.488100
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 448118 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: AC

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<a href="#">COGCC Inspection Report Summary</a> On Monday 1/19/21 at approximately 0912hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Watkins Tank Battery of Noble Energy Facility ID: 448118 in Weld County, Colorado. While there, I observed a facility that is active. No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.	burnsa	01/19/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103007	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5332750">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5332750</a>