

FORM  
5

Rev  
02/20

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402267807

Date Received:

12/23/2019

## DRILLING COMPLETION REPORT

Per Rule 308A, this form and all required attachments shall be submitted after completing the drilling operations to drill, sidetrack, or deepen a wellbore and after changing the casing and/or cement configuration of a wellbore. If any attempt has been made to test, complete, or produce the well, the operator shall also submit a Form 5A (Completed Interval Report) per Rule 308B. If the well has been plugged, the operator shall also submit a Form 6 (Well Abandonment Report) per Rule 311.

Completion Type  Final completion  Preliminary completion

OGCC Operator Number: 10459 Contact Name: Kamrin Ruder  
 Name of Operator: EXTRACTION OIL & GAS INC Phone: (720) 9747743  
 Address: 370 17TH STREET SUITE 5200 Fax: \_\_\_\_\_  
 City: DENVER State: CO Zip: 80202 Email: kruder@extractionog.com

API Number 05-014-20765-00 County: BROOMFIELD  
 Well Name: INTERCHANGE A Well Number: S22-30-12N  
 Location: QtrQtr: SWNW Section: 10 Township: 1S Range: 68W Meridian: 6  
 FNL/FSL \_\_\_\_\_ FEL/FWL \_\_\_\_\_  
 Footage at surface: Distance: 2231 feet Direction: FNL Distance: 1182 feet Direction: FWL  
 As Drilled Latitude: 39.980522 As Drilled Longitude: -104.992974  
 GPS Data: GPS Quality Value: 1.4 Type of GPS Quality Value: PDOP Date of Measurement: 11/06/2019  
 GPS Instrument Operator's Name: DANNY TUCKER  
 FNL/FSL \_\_\_\_\_ FEL/FWL \_\_\_\_\_  
 \*\* If directional footage at Top of Prod. Zone Dist: 1976 feet Direction: FNL Dist: 1377 feet Direction: FWL  
 Sec: 10 Twp: 1S Rng: 68W  
 FNL/FSL \_\_\_\_\_ FEL/FWL \_\_\_\_\_  
 \*\* If directional footage at Bottom Hole Dist: 1976 feet Direction: FNL Dist: 1377 feet Direction: FWL  
 Sec: 10 Twp: 1S Rng: 68W  
 Field Name: WATTENBERG Field Number: 90750  
 Federal, Indian or State Lease Number: \_\_\_\_\_

Spud Date: (when the 1st bit hit the dirt) 09/25/2019 Date TD: 09/25/2019 Date Casing Set or D&A: 09/25/2019  
 Rig Release Date: 09/26/2019 Per Rule 308A.b.

Well Classification:

Dry  Oil  Gas/Coalbed  Disposal  Stratigraphic  Enhanced Recovery  Storage  Observation

Total Depth MD 1633 TVD\*\* 1577 Plug Back Total Depth MD 1628 TVD\*\* 1573

Elevations GR 5232 KB 5260

Digital Copies of ALL Logs must be Attached per Rule 308A

List Electric Logs Run:

No logs to upload.

### CASING, LINER AND CEMENT

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	24	16	42	0	80	100	0	80	VISU
SURF	12+1/4	9+5/8	36	0	1,628	600	0	1,633	VISU

## STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

## FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analysis must be submitted to COGCC)
	Top	Bottom	DST	Cored	

Operator Comments:

Drilling was suspended after setting surface on this well due to economic and logistical reasons. Extraction plans to complete drilling operations on this well third quarter 2020.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Kamrin Ruder

Title: Drilling Technician Date: 12/23/2019 Email: kruder@extractionog.com

### Attachment Check List

Att Doc Num	Document Name	attached ?	
<b><u>Attachment Checklist</u></b>			
	CMT Summary *	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
402269974	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<b><u>Other Attachments</u></b>			
402267807	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
402269972	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
402269973	CEMENT JOB SUMMARY_SURFACE	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineering Tech	Passed engineering review	01/19/2021
Permit	• PBTVD corrected per Directional Survey.	11/25/2020

Total: 2 comment(s)

