

Inspection Photos

Location Name: Waag Middle SENW Pad#1

Location ID: 439215



Photo 1: Wellhead Sign



Photo 2: Stained soil not removed

Inspection Photos
Location Name: Waag Middle SENW Pad#1
Location ID: 439215



Photo 3: Wellhead Sign



Photo 4: Stained soil not removed

Inspection Photos

Location Name: Waag Middle SENW Pad#1

Location ID: 439215



Photo 5: Wellhead Sign



Photo 6: Stained soil

Inspection Photos
Location Name: Waag Middle SENW Pad#1
Location ID: 439215




Photo 7: Stained soil



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Waag Middle SENW Pad#1
Location ID: 439215



Photo 9: Stained soil removed