

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 1: Tank Battery Sign



Photo 2: Equipment removed

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 3: Sign installed



Photo 4: Sign installed



Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 5: Sign installed



Photo 6: Wellhead Sign

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976



Photo 7: Stained soil removed



Photo 8: Wellhead Sign

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976




Photo 9: Stained soil re-accumulated



Photo 10: Wellhead Sign

Inspection Photos
Location Name: Calvary Farms 19-L Pad
Location ID: 457976




Photo 11: Stained soil re-accumulated