

Inspection Photos
Location Name: Calvary Farms 19-D Pad
Location ID: 457898



Photo 1: Wellhead Sign




Photo 2: Stained Soil removed



Inspection Photos
Location Name: Calvary Farms 19-D Pad
Location ID: 457898



Photo 3: Wellhead Sign



Photo 4: Stained soil

Inspection Photos
Location Name: Calvary Farms 19-D Pad
Location ID: 457898



Photo 5: Wellhead Sign



Photo 6: Stained soil

Inspection Photos
Location Name: Calvary Farms 19-D Pad
Location ID: 457898



Colorado Oil & Gas Conservation Commission
40.56455, -104.69831, 1467.1m, 221°
Jan 13, 2021 12:24:24 PM

Photo 7: Signage installed



Colorado Oil & Gas Conservation Commission
40.56449, -104.69872, 1469.0m, 93°
Jan 13, 2021 12:24:57 PM

Photo 8: Signage installed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Calvary Farms 19-D Pad
Location ID: 457898



Photo 9: Signage installed



Photo 10: Equipment removed

Inspection Photos
Location Name: Calvary Farms 19-D Pad
Location ID: 457898



Colorado Oil & Gas Conservation Commission
40.5645, -104.69867, 1472.6m, 50°
Jan 13, 2021 12:28:19 PM

Photo 11: Stained soil removed



Colorado Oil & Gas Conservation Commission
40.56499, -104.69872, 1479.5m, 100°
Jan 13, 2021 12:30:45 PM

Photo 12: Tanks removed

