



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Fork Unit 16-5-2-1

API: 05-103-08887

Inspection: 700405078



39.90094, -108.74966, 5969.8ft, 72°
01/19/2021 03:23:25 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Fork Unit 16-5-2-1

API: 05-103-08887

Inspection: 700405078



39.90097, -108.74957, 5972.6ft, 104°
01/19/2021 03:26:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well.

Fork Unit 16-5-2-1

API: 05-103-08887

Inspection: 700405078



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Meter building, pit, tank, separator.

Fork Unit 16-5-2-1

API: 05-103-08887

Inspection: 700405078



39.90117, -108.74994, 5981.1ft, 91°
01/19/2021 03:22:00 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Pit & tank.

Fork Unit 16-5-2-1

API: 05-103-08887

Inspection: 700405078