

Interim Reclamation Inspection

January 19, 2021

Operator: RENEGADE OIL & GAS COMPANY LLC - #74165

Location ID: 322192

Inspection Document #: 697502467

Elbert County, CO

SESE Section 10 T6S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COGGINS-66S64W
Location ID: 322192



Photo 1. Photo taken of the Operator sign at the tank battery.

Inspection Photos
Location Name: COGGINS-66S64W
Location ID: 322192



Photo 2. Photo taken from the western tank battery, facing West. Photo illustrates Common mullein rosettes.



Inspection Photos
Location Name: COGGINS-66S64W
Location ID: 322192



Photo 3. Photo taken from the western tank battery, facing North. Photo illustrates unmanaged Common mullein at the adult stage, as well as Kochia.



Photo 4. Photo taken from the northern tank battery, facing East. Photo illustrates unmanaged Common mullein at the adult stage, which is spreading onto the adjacent surface owners property.



Photo 5. Photo taken from within the deadman at the well location. Photo illustrates puncture vine. Surface owner has been attempting to control but it will be the responsibility of the Operator to manage and control.

Inspection Photos
Location Name: COGGINS-66S64W
Location ID: 322192



Photo 6. Photo taken from within the deadman at the well location, facing West. See comments under Photo 5.