

Construction and Stormwater Inspection

January 20, 2021

Operator: BISON OIL & GAS II LLC - #10661

Location ID: 472549

Inspection Document #: 697502472

Weld County, CO

NWSW Section 16 T8N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 1. Drone aerial imagery illustrates the eastern location, facing East. Photo illustrates the new access road, ditch and berm BMP, and a sediment trap being completed.



Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 2. Drone aerial imagery illustrates the northeastern location, facing Northeast. Photo illustrates the ditch and berm BMP, and a sediment trap being completed.



Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 3. Drone aerial imagery illustrates the northwestern location, facing Northwest. See comments under Photo 1. Topsoil salvage operations were underway at the time of this inspection along the northern location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502472

Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 4. Drone aerial imagery illustrates the southwestern location, facing Southwest. See comments under Photo 1.



Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 5. Drone aerial imagery illustrates the southern location, facing South. Photo illustrates the topsoil stockpile.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502472

Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 6. Photo taken from the eastern location, facing South. Photo illustrates the ditch and berm BMP, which has been installed around the entire perimeter of location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502472

Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 7. Photo taken from the southern location, facing West. Photo illustrates the ditch and berm BMP and the topsoil stockpile.



Inspection Photos

Location Name: Big Mountain Viper 8-59 /16

Location ID: 472549



Photo 8. Photo taken from the northeastern location, facing South. Photo illustrates a sediment trap being completed. Rip-rap material was delivered for the tracking pad and sediment trap outlets.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697502472