

# Inspection Photos

1/19/2021

Operator: Pan American/Amoco/BP America  
Inc

Location ID: 396603  
Rio Blanco County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: Pan American/Amoco/BP America Inc

Location ID: 396603



**Photo 1:** Photo taken from the south end of the Location, facing north. Photo of well marker.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: Pan American/Amoco/BP America Inc

Location ID: 396603



**Photo 2:** Photo taken from the south end of the Location, facing northeast. Photo shows concrete block remaining on the Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: Pan American/Amoco/BP America Inc

Location ID: 396603



**Photo 3:** Photo taken from the northeast end of the Location, facing west. Photo shows pipe/anchor remaining on the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: Pan American/Amoco/BP America Inc

Location ID: 396603



**Photo 4:** Photo taken from the northwest end of the Location, facing northwest. Photo shows pipe remaining on the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Operator Name: Pan American/Amoco/BP America Inc

Location ID: 396603



**Photo 5:** Photo taken from the northwest end of the Location, facing northwest. Photo shows pipe remaining on the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Operator Name: Pan American/Amoco/BP America Inc

Location ID: 396603



**Photo 6:** Photo taken from the southwest end of the Location, facing southwest. Photo shows pipe/anchor remaining on the Location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources