

Inspection Photos

1/19/2021

Operator: EAGLE OPERATING INC - 26155

Location ID: 397227

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397227



Photo 1: Photo taken from the north end of the Location, facing southeast. Photo provides overview of the Location. Photo also shows riser identified in previous inspection has been removed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397227



Photo 2: Photo taken from the north end of the Location, facing southwest. Photo provides overview of the Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: EAGLE OPERATING INC - 26155

Location ID: 397227



Photo 3: Photo taken from the well marker. Photo shows area where subsidence concerns remain evident.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources