

Grizzly Operating GGU 6-29 Location # 335202

Jan 22, 2021 at 12:47:35 PM
39.500903,-107.580214 ±35.69m
OGCC



location

Jan 22, 2021 at 12:54:06 PM
39.500795,-107.579734 ±4.79m
OGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating GGU 6-29 Location # 335202



location



location



**Grizzly Operating
GGU 6-29
Location # 335202**



Unused chemical tank



Unused tank/stairs

Grizzly Operating GGU 6-29 Location # 335202



**Well head that has braden head tied into sales and
is no longer connected to unused tank in background**



Lack if stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
GGU 6-29
Location # 335202**



Lack of stabilization



**Lack of stabilization/Entrance/No evidence of
tracking control BMP's**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Grizzly Operating
GGU 6-29
Location # 335202**



Lack of stabilization



Entrance/No evidence of tracking control BMP's

