

# *Inspection Photos*

*Loc#324372*

*Operator: Terra*

*Insp#: 692402887*

*Insp Date: 1/13/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View of Interim area on Northwest side of Location.

January 13, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Moss Loc#324372



Photo#2:  
Facilities and equipment.



Photo#3:  
Well head area.

January 13, 2021