

Inspection Photos

API#045-06226

Operator: Terra

Insp#: 692402888

Insp Date: 1/13/21





Photo#1:
Overview of Location to Southeast.

January 13, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra AL Clough API#045-06226



Photo#2:
Culvert on access road.



Photo#3:
Access Road.

January 13, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra AL Clough API#045-06226