

Inspection Photos

API#045-13870

Operator: Terra

Insp#: 692402889

Insp Date: 1/13/21





Photo#1:
Overview of Location to Southeast.

January 13, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PR Clough API#045-13870



Photo#2:
Equipment area.



Photo#3:
Fence in disrepair.

January 13, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra PR Clough API#045-13870