

Inspection Photos

Loc#335320

Operator: Caerus

Insp#: 692402890

Insp Date: 1/13/21






Photo#1:
Overview of Location to Northeast.

January 13, 2021



Photo#2:
South corner of site.



Photo#3:
BMP area.

January 13, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Lazier Loc#335320