

Inspection Photos

Location Name: LETTERLY-USX AB-67N64W /23SWSW

Location #: 310465



Colorado Oil & Gas Conservation Commission
Weld
+40.552805, -104.524507
19° N
22-Jan-2021 12:46

Photo #1

Letterly-USX AB 23-13 (05-123-26439) Wellsite
Temporarily Abandoned | TA



Colorado Oil & Gas Conservation Commission
Weld
+40.553306, -104.526242
23° NE
22-Jan-2021 13:27

Photo #2

Letterly-USX AB 23-13 Battery site
Abandoned: ALL Equipment Removed