



Inspection Photos
Location Name: Porter UPRR 3
Location ID: 320249

an 22, 2021 at 2:48:04 PM
39.855956,-104.413768
9055 E 88th Ave
Bennett CO 80102
United States
COGCC



Pic 1 weeds

an 22, 2021 at 2:48:27 PM
39.855767,-104.413780
9055 E 88th Ave
Bennett CO 80102
United States
COGCC



Pic 2 weeds




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Porter UPRR 3

Location ID: 320249

Jan 22, 2021 at 2:53:36 PM
39.855767,-104.413780
9055 E 88th Ave
Bennett CO 80102
United States
COGCC



Pic 3 weeds



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources