



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**API: 05-103-11783 to 11790**  
**RGU 23-23-198 pad**      **Inspection: 700405149**



39.94665, -108.36266, 6494.9ft, 5°  
01/22/2021 04:51:18 PM





39.94602, -108.36245, 6499.7ft, 78°  
01/22/2021 04:53:09 PM



39.94616, -108.3622, 6497.6ft, 265°  
01/22/2021 04:48:49 PM





39.94599, -108.36251, 6491.8ft, 242°  
01/22/2021 04:53:21 PM



39.94588, -108.36268, 6502.0ft, 251°  
01/22/2021 04:54:45 PM





39.94598, -108.36275, 6500.6ft, 207°  
01/22/2021 04:55:37 PM



39.94589, -108.36267, 6500.2ft, 50°  
01/22/2021 04:55:02 PM





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 9. Stained soil outside tank battery.**

**API: 05-103-11783 to 11790**  
**RGU 23-23-198 pad**      **Inspection: 700405149**