

Inspection Photos  
Operator: Enduring  
API: 067-07840  
Date: 1/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Location largely snow covered. Taller perennial vegetation such as western wheatgrass observable through the snow.





Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of Scotch thistles observed within the project area. Approximately 200 individuals observed.





Photo 5. View of the reference area comprised of sagebrush shrubland with scattered pinyon and juniper trees, mountain mahogany, James galleta, and purple threeawn.