

Inspection Photos
Location Name: Gold 9NU
Location ID: 302527



Colorado Oil & Gas Conservation Commission
40.33185, -104.89681, 1440.3m, 67°
01/25/2021 09:03:54

Production facility



Colorado Oil & Gas Conservation Commission
40.33083, -104.89664, 1446.1m, 0°
01/25/2021 09:02:04

Wellhead

Inspection Photos
Location Name: Gold 9NU
Location ID: 302527




Master valve leak on 1/6/2021



Master valve leak on 1/25/2021

Inspection Photos
Location Name: Gold 9NU
Location ID: 302527



Lubricator leak on 1/6/2021



Lubricator leak on 1/25/2021