

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/25/2021

Submitted Date:

01/25/2021

Document Number:

693504283

FIELD INSPECTION FORM

Loc ID 302349 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298155	WELL	TA	05/04/2020	GW	123-28194	BUCKCHERRY USX AA 03-02	TA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Steel rod		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 298155 Type: WELL API Number: 123-28194 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: SITE CONDITION

Comment: At time of inspection flow lines have been removed and master valve is LOTO well is TA. Form 4 TA status is on file with the COGCC. No MIT on file. Noble Energy's Alternative Mechanical Integrity Assurance Program.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:
End Surf Csg Pressure:

Comment: Submit reports.

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<u>Routine inspection.</u>	silverr	01/25/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693504284	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5336468