

Inspection Photos

Location Name: Juanita State 1

Location ID: 320133

Jan 25, 2021 at 12:16:44 PM
39.914009,-104.505987
Bennett CO 80102
United States
COGCC



Pic 1 weeds unmanaged

Jan 25, 2021 at 12:18:22 PM
39.913281,-104.507904
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 2 weeds unmanaged

Inspection Photos

Location Name: Juanita State 1

Location ID: 320133

Jan 25, 2021 at 12:18:39 PM
39.912991,-104.507858
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 3 weeds unmanaged/trash

Jan 25, 2021 at 12:18:53 PM
39.912891,-104.507856
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 4 trash on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Juanita State 1

Location ID: 320133



Pic 5



Pic 6 open top tank with no netting



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Juanita State 1

Location ID: 320133



Pic 7 dead bird of prey in open top tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources