

Final Reclamation Inspection

January 20, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 423929

Inspection Document #: 697502476

Weld County, CO

NWNW Section 16 T8N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: MONTANA STATE PC LG #16-68HN

Location ID: 423929



Photo 1. Photo taken from the southern access road, facing North. Photo illustrates the Operator has performed final reclamation activities (i.e., removal of gravel, straw mulch, seed, etc...). However, there was no establishment of desirable vegetation. It does appear the Operator has been managing weeds.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 697502476

Inspection Photos

Location Name: MONTANA STATE PC LG #16-68HN

Location ID: 423929



Photo 2. Photo taken from a portion of the access road. Photo illustrates straw mulch.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 697502476

Inspection Photos

Location Name: MONTANA STATE PC LG #16-68HN

Location ID: 423929



Photo 3. Photo taken from a portion of the central access road, facing North. See comments under Photo 1.



Inspection Photos

Location Name: MONTANA STATE PC LG #16-68HN

Location ID: 423929




Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos

Location Name: MONTANA STATE PC LG #16-68HN

Location ID: 423929



Photo 5. Photo taken from the tank battery location, facing South. See comments under Photo 1.

